

No. Fail J2307 Jln Haji Taib 3.

Rajah di muka

Stesen	BEARING / SUDUT			Dari Stn.	GARISAN		Ke Stn.	Sudut Pukak (±)	Jarak	Suhu	Jarak Antara Tupang	Jarak Muktamat
	Penyilang Kiri	Penyilang Kanan	Purata		Bearing Muktamat							
	Datum Daripada			20	1875502		2	4	11207	9/11/21		11207
	PB 127 m/s 15											
	(Demorete)											
20-30	204909			20	204909	30	4	4	21.029		77	21.029
20-31	202518			20	202518	31	4	4	20.988		pkB (RM)	20.988
20-32	271535			20	271535	32	4	4	19.515		pkB	19.515
20-33	290155			20	290155	33	4	4	13.903		pkB	13.903
20-34	450519			20	450519	34	4	4	8.162		pkB	8.162
20-35	613318			20	613318	35	4	4	11.090		pkB	11.090
20-36	425913			20	425913	36	4	4	15.363		pkB	15.363
20-37	890502			20	890502	37	4	4	28.935		pkB	28.935
20-38	710903			20	710903	38	4	4	31.331		pkB	31.331
20-39	610210			20	610210	39	4	4	39.830		pkB	39.830
	(Grid Line)											
20-40	193872			20	193872	40	4	4	20.619		pkB	20.619
20-41	495559			20	495559	41	4	4	27.505		pkB	27.505
20-42	615905			20	615905	42	4	4	35.057		pkB	35.057
20-43	731309			20	731309	43	4	4	31.355		pkB	31.355
20-44	630221			20	630221	44	4	4	22.603		HWP	22.603
20-45	267510			20	267510	45	4	4	13.390		pkB	13.390
20-46	492547			20	492547	46	4	4	7.967		pkB	7.967
20-47	792350			20	792350	47	4	4	19.680		pkB	19.680
20-48	851513			20	851513	48	4	4	29.318		pkB	29.318