

No. Fail JRS80911 SS-9

Rajah di muka

Stesen	BEARING / SUDUT			Dari Stn.	GARISAN Bearing Muktamat	Ke Stn.	Sudut Pugak (±)	Jarak	Suhu	Jarak Antara Tupang	Jarak Muktamat
	Penyilang Kiri	Penyilang Kanan	Purata								
	Datim Daripada PA		39 39 21	2	39 39 21	1	4	29.995	20/0/09		29.995
				pk-B		BKL					
2-3	117 39 19			2	117 39 19	3	4	21.036		BKL	21.036
2-4	182 07 28			2	182 07 28	4	4	71.233		pk-L ←	71.233
2-5	193 09 52			2	193 09 52	5	4	5.998		pk-L ←	5.998
2-6	30 01 36			2	30 01 36	6	4	27.577		pk-B	27.577
	1 39 39 21	219 39 21	99 44 09	2	99 44 09	7	4	39.996			39.996
2											
	7 99 44 09	279 44 09									
	pk-L										
7-8	132 13 26			7	132 13 26	8	4	13.788		BKL	13.788
7-9	22 54 32			7	22 54 32	9	4	26.189		pk-L ←	26.189

5-9 65 31 51 56.011 ~
65 32 59 56.022 po
-1 8" -0.01/

5-108 101 07 42 51.747 ~
5-8 101 07 57 51.759 po
-15" -0.007

No. Fail

Rajah di muka

[illegible]

DAERAH DETAKING.
MUKIM SUNGAI BUKAH
85C
TANPA SKACA

