

No. Fail 45005. SunShine Villa.

Rajah di muka

[illegible]

No. Fail

Rajah di muka

[illegible]

Rajah di muka

Stesen	BEARING / SUDUT			Dari Stn.	GARISAN Bearing Muktamat	Ke Stn.	Sudut Pukak (±)	Jarak	Suhu	Jarak Antara Tupang	Jarak Muktamat
	Penyilang Kiri	Penyilang Kanan	Purata								
107 112	78 53 05	228 53 05	179 53 05	112	179 53 05	113	4	7.805			7.805
113	179 57 05	359 57 05									
	BKL										
107 112	Seperiti Di Atas	379 30 22	112	379 30 22	119	4	30.912				30.912
119	379 30 22	169 30 22									
	PKT										

No. Fail

Rajah di muka

Stesen	BEARING / SUDUT			Dari Stn.	GARISAN Bearing Muktamat	Ke Stn.	Sudut Pugak (±)	Jarak	Suhu	Jarak Antara Tupang	Jarak Muktamat
	Penyilang Kiri	Penyilang Kanan	Purata								

Sarah Port Dickson.
 Jalan Teluk Kenang.
 Sebyan 1
 Tanpa Skala.

Remerk:

Sta 1-19 Dipetik dtd. FB's chng.
 m/s 35.

113-8 165 73 38 151.678N
 165 73 28 151.629PO
 +10" 70.099

113-13 162 09 10 76.095N
 162 03 89 76.039PO
 +28" 70.001



Tarikh

Aras

Dibuat untuk

38

Daripada

Ke

XXXXXX

Pandangan Belakang	Pandangan Antara	Pandangan Hadapan	Naik	Turun	Aras Yang Dilaras	Jarak	Catitan
1.083 (3.92)	1.377 (7.52)	1.906 (7.38)		6.507 7.41			7.41 7.41 (1.11) 6.507 7.41 6.507
1.377 (7.52)	1.377 (7.38)			6.178 7.2			7.2
1.086 (3.58)	1.623 (5.32)			6.878 7.41			7.41 7.41 (1.11) 6.507 7.41 6.507
2.786 (8.07)	1.623 (5.32)			5.323 7.41			7.41 7.41 (1.11) 6.507 7.41 6.507
1.578 (5.18)	1.785 (5.79)			6.156 7.41			7.41 7.41 (1.11) 6.507 7.41 6.507
	1.975 (6.78)			6.528 7.41			7.41 7.41 (1.11) 6.507 7.41 6.507
6.988	6.888			6.127 7.41			7.41 7.41 (1.11) 6.507 7.41 6.507