

No. Fail 15420 Bahay

Rajah di muka

BEARING SIGHT			Dian Stn	GARISAN		Ke Stn	Sudut Papan (°)	Jarak	Suhu	Jarak Antara Papan	Jarak Mukamat
Langit Kiri	Langit Kanan	Pusat		Bearing Mukamat							
Datum Danpada			1	89 51 11	5	4	125.910	29/2/2011			125.910
			pk-L		pk-L						
5	89 51 11	289 51 11	139 53 23	1	139 53 23	50	4	57.637			57.637
1											
50	139 53 23	349 53 23									
			BKL								
1	349 53 23	139 53 23	87 19 53	50	87 19 53	51	4	111.191			111.191
50											
51	87 19 53	287 19 53									
			pk-L								
50-52	1 39 91			50	1 39 91	52	4	28.552		BKL	28.552
50-53	333 28 83			50	333 28 83	53	4	32.266		BKL	32.266
50-57	272 38 30			50	272 38 30	57	4	15.276		BKL	15.276
50-55	92 33 25			50	92 33 25	55	4	18.997		BKL	18.997
50	287 19 53	87 19 53	329 02 26	51	329 02 26	5	4	78.259			78.259
51											
5	329 02 26	149 02 26									
51-56	208 08 26			51	208 08 26	56	4	11.277		BKL	11.277
51-57	37 31 51			51	37 31 51	57	4	70.830		BKL	70.830
5-58	119 50 32			5	119 50 32	58	4	6.689		BKL	6.689
5-59	159 07 98			5	159 07 98	59	4	15.919		BKL	15.919
51	149 02 26	329 02 26	289 51 11	5	289 51 11	1	Si/4	Li/4 + 1.1.			
5											
1	289 51 11	89 51 11									
					Bering						
					Terdurup.						

