

No. Fail SEL 572 Ba/a key

Rajah di muka

Stesen	BEARING / SUDUT			Dari Stn.	GARISAN		Ke Stn.	Sudut Pukak ($\pm$)	Jarak	Syhu	Jarak Antara Tiang	Jarak Muklumat
	Penyilang Kiri	Penyilang Kanan	Purata		Bearing Muklumat							
	Datun Daripada			2	187 08/1	1	H	150.638	15/1/2020			150.638
				pkB	Aj Ak.	pkB						
					187 08/1							
2-3	7 180/			2	7 180/	3	H	18.778		pk.L		18.778
2-4	3 1039			2	3 1039	4	H	10.735		pk.L		10.735
2-5	186 7836			2	186 7836	5	H	62.757		pk.L		62.757
2-6	186 7527			2	186 7527	6	H	79.612		pk.L		79.612
2	7 08/1	187 08/1	185 0370	1	185 0370	7	H	71.023				71.023
1	185 0370	5 0370										
	pk.B											
1-8	15/28/1			1	15/28/1	8	H	7.868		pk.L		7.868
7-9	25/7/07			7	25/7/07	9	H	8.095		pk.L		8.095
7-10	203 7635			7	203 7635	10	H	29.737		pk.L		29.737
7-11	15/760/			7	15/760/	11	H	3.771		pk.L		3.771

