

SEK 908 Jln Kebun (Sembra)

No. Fail

Rajah di muka

Stesen	BEARING / SUDUT			Dari Stn.	GARISAN Bearing Mukamat	Ke Stn.	Sudut Pukak (±)	Jarak	Suhu	Jarak Antara Tupang	Jarak Mukamat
	Penyilang Kiri	Penyilang Kanan	Purata								
	Datiyam Danipada.								25/10/2008		
		296 261	2	296 261	1	4	151.871				151.871
			pkB		pkL (78m)						
1	296 261	116 261	93 08 32	2	93 08 32	3	4	185.679			185.679
2						pkL (78m)					
3	93 08 32	273 08 32									
			pkL (78m)								
1	296 261	116 261	79 50 73	2	79 50 73	7	4	186.751			186.751
2											
7	79 50 73	259 50 73									
			pkB								
2-5	325 19 87			2	325 19 87	5	4	167.200		BL	167.200
2-6	296 93 25			2	296 93 25	6	4	138.679		BL	138.679
2-7	280 00 92			2	280 00 92	7	4	190.999		BL	190.999
2-8	277 92 27			2	277 92 27	8	4	191.730		BL	191.730
2	259 50 73	79 50 73	2 07 57	7	2 07 57	9	4	59.570		P	59.570
7											
9	2 07 57	182 07 57									
			pkB								
4-10	289 35 16			7	289 35 16	10	4	19.817		BL	19.817
4-11	190 10 73			7	190 10 73	11	4	2.252		BL	2.252
4-12	155 06 13			7	155 06 13	12	4	17.208		BL PL	17.208
4-13	123 13 13			7	123 13 13	13	4	10.912		PL	10.912

No. Fail

Rajah di muka

Stesen	BEARING / SUDUT		Dari	GARISAN	Ke	Sudut Pugak	Jarak	Suhu	Jarak Antara Tupang	Jarak Mukamat
	Penyilang Kiri	Penyilang Kanan	Purata	Stn.	Bearing Mukamat	Stn.	(±)			
	MYKIM KLANG.					6-12	97 41 09	316.515	N	
	DAERAH KLANG.						97 41 01	316.528	PO	
	TANPA SKALA						73°	-0.009		

542	20 5617	80.7632
	20 5600	80.76800
	717	-0.005

