

Demarcation.

No. Fail SEL 18 Ampang Tokong

Rajah di muka

Stesen	BEARING / SUDUT			Dari Stn.	GARISAN		Ke Stn.	Sudut Pugak (±)	Jarak	Suhu 13/5/65	Jarak Antara Tupang	Jarak Mul
	Penyilang Kiri	Penyilang Kanan	Purata		Bearing Muktamat							
1	Bering Daripada	A	195 00 00	2	193 22 00	1	1/	90.962				90.
2			M-1 38 00									
1	195 00 00	15 00 00	329 31 20	2	327 53 20	3	4	9.551				9.55
2			M-1 38 00									
3	329 31 20	199 31 20										
	S/L											
1	S. S. A	102 26 32	2	100 98 32	7	4	38.579					38.5
2			M-1 38 00					38.570				
7	102 26 32	282 26 32										
	pt.B											
2	282 26 32	102 26 32	333 98 30	7	332 10 30	5	4	27.832				27.8
7			M-1 38 00									
5	333 98 30	153 98 00										
	AK											
2	S. S. A.	182 17 38	7	180 39 38	6	4	105.023					105.0
7			M-1 38 00					105.023				
6	182 17 38	2 17 38										
	pt.B											
7	2 17 38	182 17 38	299 98 09	6	293 10 09	1	4	58.939				58.9
6			M-1 38 00					58.939				
1	299 98 09	119 98 09										
6	119 98 09	299 98 09	15 00 00	1	13 22 00	2	Sila Rujuk	11				
1			M-1 38 00									
2	15 00 00	195 00 00			Bering Terakhir.							

Bering 1-2 dibaca 15 00 00
 Segitujanya dibaca 15 00 00
 Tikaian N:/
 Ambekulan N:/

No. Fail

Rajah di muka

Sen	BEARING / SUDUT			Dari Stn.	GARISAN Bearing Muklumat	Ke Stn.	Sudut Pugak (±)	Jarak	Suhu	Jarak Antara Tupang	Jarak Muklumat
	Penyilang Kiri	Penyilang Kanan	Purata								
6	119 78 09	299 78 09	278 73 00	1	277 05 00	7	H	57.931			57.931
			M-1 78 00								
7	278 73 00	38 73 00									
	AKL										
6	S. D. A.	379 33 37		1	372 55 37	8	H	17.700			17.700
		M-1 38 00									
8	379 33 37	139 33 37									
	AL							58.738	19/5/05		
1	293 10 09	113 10 09		6		9	H	53.606			53.606
									3599.740		
9	781757								7072	506	

No. Fail

Rajah di muka



