

No. Fail SEL 257 melawati Upgrade Survey.

Rajah di muka

Stesen	BEARING / SUDUT			Dari Stn.	GARISAN	Ke Stn.	Sudut Pukak (±)	Jarak	Suhu	Jarak Antara Tumpang	Jarak Mukamat
	Penyilang Kiri	Penyilang Kanan	Purata		Bearing Mukamat						
1	Bering Dangpa da	191 1753	2	191 1753	1	87 01	128.768	128.768	128.768		
2											
1	191 1953	21 1953	5 35 37	2	5 35 37	101 69 25	100.097	100.097			
2							100.099				
101	5 35 37	185 35 37									
	pkt										
2	185 35 37	5 35 37	302 19 57	101	302 19 59	102 88 50	51.890	51.890			
101			" - 3				51.891				
102	302 19 57	122 19 57									
	pkt										
101	122 19 57	302 19 57	299 02 02	102	299 01 56	103 99 02	126.168	126.168			
102			" - 6				126.168				
103	299 02 02	119 02 02									
	pkt										
102	119 02 02	299 02 02	295 29 99	103	295 29 35	109 102 18	96.978	96.978			
103			" - 9				96.979				
109	295 29 99	115 29 99									
	pkt										
102	Seperti Di Atas	329 18 98	103 329 18 39	105 98 09	19.666		19.666				
103		M- 9									
105	329 18 98	199 18 98									
	PL										
102	Seperti Di Atas	319 19 59	103 319 19 45	106 98 97	8.991		8.991				
103		M- 9									
106	319 19 59	139 19 59									
	PL										

No. Fail

Rajah di muka

[illegible]

Rajah di muka

[illegible]

No. Fail

Rajah di muka

[illegible]

Rajah di muka

[illegible]

No. Fail

Rajah di muka

[illegible]

[illegible]