

No. Fail D47 W788 Jinjang

Rajah di muka

Stesen	BEARING / SUDUT			Dari Stn.	GARISAN		Ke Stn.	Sudut Pukak ($\pm$)	Jarak	Suhu	Jarak Antara Tupang	Jarak Mukamat
	Penyilang Kiri	Penyilang Kanan	Purata		Bearing Mukamat							
	Datum Banjaruda			2	3 06 50	1	4	20.050	25/8/15		20.050	
				pkL		Sp.						
1	3 06 50	183 06 50	102 37 05	2	102 37 05	3	4	33.001			33.001	
2												
3	102 37 05	282 37 05										
	pk.B											
2	282 37 05	102 37 05	353 05 49	3	353 05 49	4	4	31.829			31.829	
3												
4	353 05 49	173 05 49										
	pk.B											
3-5	300 08 36			3	300 08 36	5	4	13.189		Sp.L	13.189	
3-6	329 07 28			3	329 07 28	6	4	12.861		Sp.L	12.861	
4-7	198 53 17			4	198 53 17	7	4	6.206		Sp.L	6.206	
3	173 05 49	353 05 49	280 59 07	4	280 59 07	1	4	27.690			27.690	
4												
1	280 59 07	80 59 07										
4	80 59 07	280 59 07	183 06 50	1	183 06 50	2	Sik Lilit R1					
1					Bering Tertutup.							
2	183 06 50	3 06 50										
	Bering 1-2 Di bare 183 06 50											
	Sepatutnya Di bare 183 06 50											
	Tikatan Ni/											
	Am betul Ni/											

WILAYAH PERSEKUTUAN
MUKIM BATU
TANPA SKALA

Rajah di muka

No. Fail

