

No. Fail P473386 Antara Gapi 1st

Rajah di muka

Stesen	BEARING / SUDUT			Dari Stn.	GARISAN	Ke Stn.	Sudut Pukak ($\pm$)	Jarak	Suhu	Jarak Antara Tupang	Jarak Mukamat
	Penyilang Kiri	Penyilang Kanan	Purata		Bearing Mukamat						
	Datun	Demput		C	339 55 86	1	4	207.919	6/11/16		207.919
				pk	A ₃ Ak.		BL				
					Sgn MY						
1	339 55 86	159 55 86	203 22 03	2	203 22 03	3	4	179.389			179.389
2											
3	203 22 03	23 22 03									
				pk							
2	23 22 03	203 22 03	289 53 93	3	289 53 93	4	4	102.217			102.217
3											
				4	269 53 93	89 53 93					
				pk							
3-5	328 98 22			3	328 98 22	5	4	209.319		BL	209.319
3-6	399 38 01			3	399 38 01	6	4	180.623		PL	180.623
4-7	278 19 00			4	278 19 00	7	4	16.920		PL	16.920
	Demarcate.										
4-8	19 55 09			4	19 55 09	8	4	39.396		AB	39.396

