

No. Fail JM 1897 Sg Buluh.

Rajah di muka

Stesen	BEARING / SUDUT			Dari Stn.	GARISAN	Ke Stn.	Sudut Pukak (±)	Jarak	Suhu	Jarak Antara Papan	Jarak Mukamat
	Penyilang Kiri	Penyilang Kanan	Purata		Bearing Mukamat						
○	Datun	Daipada		2	280 2529	1	4	111.833	19/8/2017		111.833
					pkB Az Ak. pkB						
					Gym M4						
1	280 2529	80 2529	139 0520	2	139 0520	3	4	79.727			79.727
2											
3	139 0520	318 0520									
	pkA										
2-4	72 2150			2	72 2150	4	4	10.073		pkC	10.073
2-5	87 5250			2	87 5250	5	4	72.550		BKL	72.550
2-6	95 2829			2	95 2829	6	4	63.367		BKL	63.367
2	318 0520	139 0520	185 5723	3	185 5723	7	4	112.906			112.906
3											
7	185 5723	5 5723									
	pkA										
3	5 5723	185 5723	158 0390	7	158 0390	8	4	69.679			69.679
7											
8	158 0390	338 0390									
	pkA										
3	Sprute Di. Aka	208 7605		7	208 7605	9	4	66.859			66.859
7											
9	208 7605	28 7605									
	pkA										
8-10	51 5993			8	51 5993	10	4	7.890		BKL	7.890
9-11	201 0650			9	201 0650	11	4	11.673		AB	11.673
2-12	208 3710			2	208 3710	12	4	12.026		AB	12.026
2-13	102 1993			2	102 1993	13	4	33.397		AB	33.397

[illegible]

