

No. Fail JM 2103 Hi Tek 6 Semangih

Rajah di muka

Stesen	BEARING / SUDUT			Dari Stn.	GARISAN		Ke Stn.	Sudut Pukak ($\pm$)	Jarak	Suhu	Jarak Antara Tupang	Jarak Mukamat
	Penyilang Kiri	Penyilang Kanan	Purata		Bearing Mukamat							
	Datum Daripada			2	2693902	1	4	96.977	10/12/15		96.977	
					A3 Ak.							
					A31 MH							
2-3	2561207			2	2561207	3	4	99.626		BKL	99.626	
2-4	2825220			2	2825220	4	4	95.992		BKL	95.992	
2-5	2805015			2	2805015	5	4	103.325		BKL	103.325	
1	2693902	893902	3562037	2	3562037	6	4	59.890			59.890	
2	6 3562037 1762037											
	pk.B											
1	Seperti Di Atas	793932		2	793932	7	4	50.393			50.393	
2	7 793932 2593932											
	pk.B											
2-10	3210617			2	3210617	10	4	20.951		pk.B	20.951	
2-11	995531			2	995531	11	4	37.999		pk.B	37.999	
7-12	3281130			7	3281130	12	4	20.022		pk.B	20.022	
7-13	3581825			7	3581825	13	4	31.652		pk.B	31.652	
6-14	2062859			6	2062859	14	4	27.327		pk.B	27.327	
6-15	2292956			6	2292956	15	4	38.372		pk.B	38.372	
6-16	125893			6	125893	16	4	21.396		pk.B	21.396	

