

[illegible]

No. Fail

Rajah di muka

Stesen	BEARING / SUDUT			Dari Stn.	GARISAN	Ke Stn.	Sudut Pugar ($\pm$)	Jarak	Suhu	Jarak Antara Tupang	Jarak Mukamat
	Penyilang Kiri	Penyilang Kanan	Purata		Bearing Mukamat						
18 21	80 36 05	280 36 05	277 38 96	21	277 39 32	2	H	50.725			50.725
2	277 38 96	97 38 96	C1 96								
21 2	97 38 96	277 38 96	195 35 36	2	195 36 27	1	Sila Lihat mls 7 R1				
1	195 35 36	325 35 36	C1 31								

Bering 2-1	Dibaca	1753536
Sepatu	Dibaca	1753627
Tikar		-51" uk 11 stn.
Ambutulan		7.68" per stn

Demarcação (Refin)

2-50	161 2016	28.333	pt. B	(Refix old mark)	str 3
2-51	116 3858	87.133	DB		
2-52	153 1852	59.919	pt. B	(Refix old mark)	str 9
7-53	279 0859	19.744	BKL	(Refix BKL str 9)	
7-54	80 1132	20.320	BKL	(Refix BKL str 10)	
13-55	270 2723	39.586	BKL	(Refix BKL str 10)	

No. Fail

MYKIM SABA/
DAERAH BENTONG.

Rajah di muka

TANPA SKALA

