

No. Fail JM 009 Nilai Gini 1

Rajah di muka

Stesen	BEARING SUDUT			Dori Stn	SARISAN Bearing Mukamat	R Stn	Jarak Hubung	Jarak	Jarak Antara Terdak
	Penyangkit kiri	Penyangkit kanan	Rata						
1102	1 39 0007	219 0007		1102	39 00 07	1	4	93.759	93.759
1102	1 39 0007	219 0007	290 98 96	1102	290 98 96	2002	4	78.31	78.31
2002	290 98 96	110 98 96							
3002-A	150 5902	25.219	HWP	(GL K)					
B	152 3723	30.299	HWP	(GL 3)					
C	169 9550	33.717	HWP	(GL 2)					
D	179 1999	38.295	HWP	(GL 1)					
E	181 9932	36.965	HWP	(GL K)					
F	222 1709	8.159	HWP						
G	222 1338	10.659	HWP	(GL 3)					
H	222 0852	18.229	HWP	(GL 2)					
I	222 0655	25.729	HWP	(GL 1)					
J	222 0630	28.229	HWP						
K	297 9723	33.135	HWP	(GL A")					
L	299 8593	36.218	HWP	(GL 3)					
M	289 1551	39.122	HWP	(GL 2)					
N	275 2998	93.130	HWP	(GL 1)					
O	270 9316	92.759	HWP	(GL A")					