

J2089S by Melayu Subang

No. Fail

Rajah di muka

Stesen	BEARING / SUDUT			Dari Sta	GARISAN		Ke Sta	Sudut Pukak (°)	Jarak	Suhu	Jarak Antara Pipang	Jarak Mukamat
	Penyilang Kiri	Penyilang Kanan	Purata		Bearing Mukamat							
	Datum	Danipada		2	250 1951		1	4	76.298			76.298
					A3 Ak.							
					Dgn MH							
1	250 1951	70 1951	99 5309	2	99 5309		3	4	60.903			60.903
2												
3	99 5309	229 5309										
		pkt.										
2	229 5309	99 5309	286 3736	3	286 3736		4	4	36.059			36.059
3												
4	286 3736	106 3736										
		pkt.										
2	Seperti Di Atas	70 3209		3	70 3209		5	4	73.986			73.986
3												
5	70 3209	250 3209										
		pkt. B										
3	250 3209	70 3209	62 1326	5	62 1326		6	4	69.921			69.921
5												
6	62 1326	292 1326										
		pkt. B										
5	292 1326	62 1326	82 3136	6	82 3136		7	4	61.719			61.719
6												
7	82 3136	282 3136										
		pkt.										
7-8	26 0917			7	26 0917		8	4	8.190		Sp-L	8.190
7-9	85 3910			7	85 3910		9	4	37.070		Sp-L	37.070
1-10	299 0710			1	299 0710		10	4	26.088		PL	26.088
1-11	39 2216			1	39 2216		11	4	32.883		BKL	32.883

[illegible]

Tarikh

5/2 08/15

Aras

Daripada

Dibuat untuk

BM 82131 RC: 22.802

Ke

BM 82131

21

Syams

Pandangan Melakang	Pandangan Antara	Pandangan Hadapan	Naik	Turun	Aras Yang Dilaras	Jarak	Catitan
1.733	(5.69)				16.999	BM 82263	BM 82131 RC: 22.802
	1.687	(15.53)			17.095	F2	8AS = 22.700m
	1.113	(13.65)			17.619	F1	
		0.795	(11.62)		18.237	BM 82264	BM 82131 RC: 22.802
1.538	(15.03)				18.237	BM 82264	
1.551	(15.07)	0.559	(11.89)				
2.153	(17.06)	1.652	(15.92)				
1.512	(14.96)	1.752	(15.75)				
1.556	(15.11)	1.822	(14.82)				
1.518	(14.98)	0.955	(13.13)				
1.516	(14.97)	1.917	(14.65)				
1.598	(15.29)	1.526	(15.01)				
1.559	(15.11)	0.299	(10.98)				
0.576	(11.89)	2.156	(17.07)				
1.596	(15.07)	0.176	(10.58)				
1.515	(14.97)	1.537	(15.09)				
		0.668	(10.22)		22.802		
18.139	(18.96)	13.509	(14.51)				BM 82131 RC: 22.802m