

No. Fail JE1225 Batang Kali

Rajah di muka

Stesen	BEARING / SUDUT			Dari Stn	GARISAN		Ke Stn	Sudut Pukak (±)	Jarak	Suhu	Jarak Antara Tumpang	Jarak Mukamat
	Penyilang Kiri	Penyilang Kanan	Purata		Bearing Mukamat							
	Dalam Dapada	98 5930	20	98 5930				4	61.881	16/5/013		61.881
	AB			pkB		pkL (RM)						
20	98 5930	278 5930	20 2856	20				4	37.989			37.989
	20 2856	200 2856				pkL (RM)						
20	98 5930	278 5930	250 3829	20	250 3829	50		4	71.915			71.915
	50 250 3829	70 3829			Ag 16. Ag 14							
20	70 3829	250 3829	278 5530	50	278 5530	51		4	103.039			103.039
50	51 278 5530	96 5530										
	pkL											
50	96 5530	278 5530	181 4206	51	181 4206	52		4	77.629			77.629
51	52 181 4206	1 4206										
	pkL											
50	Seperti di Atas	388 0926	51	388 0926	53			4	68.139			68.139
51	53 388 0926	168 0926										
	pkL											
51-59	186 0353			51	186 0353	59		4	58.128		BL	58.128
51-55	186 5626			51	186 5626	55		4	23.337		BL	23.337
51-56	388 0089			51	388 0089	56		4	60.165		AL	60.165
53-57	278 2359			53	278 2359	57		4	45.613		BL	45.613

Tarikh 02/12/25

Aras

Dibuat untuk

67

Daripada Batang Kalir

Ke

Pandangan Belakang	Pandangan Antara	Pandangan Hadapan	Naik	Turun	Aras Yang Dilaras	Jarak	Catitan
0.929	(1303)	(1501)			35.037	F 51	
	1.528	(1501)			39.933	78m F2397	Aku BL
2113	(1693)	1.156	(1379)		39.805		
	1.581	(1512)			35.357	F 50	
1.562	(1512)	0.209	(10.82)		36.719	F 20	
		1.963	(19.84)		36.813	78m F1708	F 1/2011 RC: 38.843m
4.579		2.823					
1.583	(15.12)				39.933	78m F2397	Aku BL
1.621	(15.32)	1.581	(15.19)		39.915		
1.728	(14.69)	1.617	(15.31)		39.719		
		1.787	(19.84)		39.360	78m F2398	Aku BL
9.602		9.685					

Aku The Rights Reserved
on my B2392.