

No. Fail *J2127 W Jln Tempinis 2 (Bangsar).*

Rajah di muka


Stesen	BEARING / SUDUT			Dari Stn.	GARISAN		Ke Stn.	Sudut Pukak (°)	Jarak	Suhu	Jarak Antara Pukak	Jarak Muktamat
	Penyilang Kiri	Penyilang Kanan	Purata		Bearing Muktamat							
	Antara Bangsari			2	319 5958	1	4	33.131		19/8/2009		33.131
				pkB		pkB						
	1	319 5958	139 5958	76 1906	2	76 1906	3	4	36.169			36.169
2	3	76 1906	226 1906									
		pkB										
2-4		190 9095		2	190 9095	9	4	6.599			5.2	6.599
2-5		99 1539		2	99 1539	5	4	8.323			5.2	8.323
2-6		55 2923		2	55 2923	6	4	30.312			5.2	30.312
	2	226 1906	76 1906	320 9008	3	320 9008	7	4	31.879			31.879
3	7	320 9008	190 9008									
		pkB										
	3	190 9008	320 9008	186 169	7	186 169	8	4	13.368			13.368
7	8	186 169	6 169									
		pkL										

No. Fail

Rajah di muka

Stesen	BEARING, SUDUT			Dari Stn	GARISAN	Ke Stn	Sudut Pukak (°)	Jarak	Suhu	Jarak Antara Tupang	Jarak Muklarnat
	Penyalang Kiri	Penyalang Kanan	Pusat		Bearing Muklarnat						
8-5	179 06 58	37 16 5 N									
	179 06 57	37 16 2 PO									
	71°	+0.002									
8-6	133 05 17	28 02 0 N									
	133 06 38	28 08 9 PO									
	-1 12°	-0.029									

WAKAYAH DERSEKUTUAN
MYKIM KUALA KUMPUR
TANPA SKA CA



Tarikh

J2127

Aras

Dibuat untuk

75

Daripada

Bangsan D/h Tempinai 2

Ke

Pandangan Belakang	Pandangan Antara	Pandangan Hadapan	Naik	Turun	Aras Yang Dilaras	Jarak	Catitan
1.630	(15.35)				78.667	GPS 1	
1.608	(15.28)				78.629	78M F2361	
1.678	(15.56)				78.591	F 1141	GPS Level on GPS + 36.270m
3.825	(11.84)	1.361	(14.97)		78.876	F 1139	Bm Level 36.168m
	2.286	(17.50)			50.015	78M F2362	constant -0.106
	2.228	(17.31)			50.073	F1	
		1.592	(15.22)		50.709	F2	GPS Level GPS 1 78.713 + constant -0.106
1.188	(3.90)				36.169	GPS X	
		1.330	(14.36)		36.022	Bm W 5023	