

No. Fail

Rajah di muka

Stesen	BEARING / SUDUT			Dari Stn.	GARISAN	Ke Stn.	Sudut Pukak (±)	Jarak	Suhu	Jarak Antara Tupang	Jarak Mukhtamat
	Penyilang Kiri	Penyilang Kanan	Purata		Bearing Mukhtamat						
	Datym	Danipack		2	203 18 56	1	4	115.926	10/12/2003		115.926
				pk B		BKL					
2	1 203 18 56	23 18 56	208 55 07	2	208 55 07	3	4	79.670			79.670
	3 208 55 07	28 55 07									
	pk B										
2	1 Sperti Di Atas	100 50 30		2	100 50 30	7	4	70.889			70.889
	7 100 50 30	280 50 30									
	pk B										
2-5	193 58 58			2	193 58 58	5	4	73.127		BKL	73.127
2-6	176 22 99			2	176 22 99	6	4	20.799		BKL	20.799
4-7	150 53 50			7	150 53 50	7	4	10.350		PL	10.350
7-8	192 27 30			7	192 27 30	8	4	31.157		PL	31.157
2-9	86 00 08			2	86 00 08	9	4	13.109		BKL	13.109

72/58

Aras

Dibuat untuk

49

Tarikh

Blue water

Daripada

Ke

Pandangan Belakang	Pandangan Antara	Pandangan Hadapan	Naik	Turun	Aras Yang Dilaras	Jarak	Catitan
1.576	(1511)	(1447)			76.328	78M F2467	Atas Longkang.
	1.362				76.592	F2	
		1.816	(1536)		76.288	78M F2468	GPS
							All the right base on BM 85336
							Level on BM 85336
							GPS Level : 72.690m
							BM Level : 72.585m
							redund 70.105m
							Level on 78M F2468
							GPS Level : 76.383m
							redund : -0.105m
							76.288m