

J2 109 RM 5 Floor → 9 Floor

No. Fail

Rajah di muka

Stesen	BEARING / SUDUT			Dari Stn.	GARISAN		Ke Stn.	Sudut Pugak (±)	Jarak	Suhu	Jarak Antara Tiang	Jarak Muktamat
	Penyilang Kiri	Penyilang Kanan	Purata		Bearing Muktamat							
5129 (5123)	}	RM on 5 th Floor		5123	0 73 36	5129	H	46.206	27/1/2017			46.206
				pt.B		pt.B						
23-5201				5123	0 17 26	5201	H	70.599			RM 1	70.599
23-5202				5123	1 43 37	5202	H	6.588			RM 2	6.588
23-5118				5123	310 33 35	5118	H	10.139			RM 3	10.139
91 (70)				70	359 25 08	91	H	39.932				39.932
				pt.B		pt.B						
70-9201				70	359 47 17	9201	H	70.612			RM 1	70.612
70-9202				70	358 37 58	9202	H	6.596			RM 2	6.596
70-9203				70	307 18 31	9203	H	10.916 10.919			RM 3	10.919
J2 109				RM (13 Floor) - base on RM 2								
131 (130)				130	359 48 38	131	H	39.095				39.095
130-1301				130	0 06 55	1301	H	70.091			RM 1	70.091
130-1302				130	0 41 27	1302	H	6.089			RM 2	6.089
130-1303				130	208 18 78	1303	H	9.999			RM 3A	9.999