

D50

JR1818 Dtm Hills Lot 33512.

No. Fail.....

Rajah di muka.....

Stesen	BEARING / SUDUT			Dari Stn.	GARISAN		Ke Stn.	Sudut Pukak (±)	30/3/2019		Jarak Antara Tupang	Jarak Muktamat
	Penyilang Kiri	Penyilang Kanan	Purata		Bearing Muktamat				Jarak	Suhu		
○	Datum Daripada			2	53 283/	1	H	60.780			60.780	
				pk.B	A2 Ak. BKL							
					Bgn MY							
2	1	53 283/	233 283/	301 2702	2	301 2702	3	H	65.330		65.330	
	3	301 2702	121 2702									
		pk.B										
2	1	Spork Di Atas		253 759/	2	253 759/	7	H	70.595		70.595	
	7	253 759/		73 759/								
		pk.										
2-5		309 239/			2	309 239/	5	H	12.708	BKL	12.708	
2-6		329 315/			2	329 315/	6	H	7.965	BKL	7.965	
2-7		272 5136			2	272 5136	7	H	21.670	BKL	21.670	
2		73 759/		253 759/	7	191 5925	8	H	25.882		25.882	
7		191 5925		11 5925								
		pk.										
8-9		200 3930			2	200 3930	9	H	17.970	PL	17.970	
8-10		117 2920			8	117 2920	10	H	30.789	PL	30.789	
○												

Rajah di muka

[illegible]

No. Fail

Rajah di muka

[illegible]