

No. Fail JZ 299 SDB SS2 Leave.

Rajah di muka

Stesen	BEARING / SUDUT			Dari Stn.	GARISAN		Ke Stn.	Sudut Pugak ($\pm$)	Jarak	Suhu	Jarak Antara Tupang	Jarak Muktamat
	Penyilang Kiri	Penyilang Kanan	Purata		Bearing Muktamat							
	Datum Daripada			2	105 085	1	4	79.679	5/5/15			79.679
				GR1		GR2						
				pkL		pkL						
1	105 085	285 085	289 992	2	289 992	3	4	183.322				183.322
2					pk							
3	289 992	109 992										
	pkB											
2-4	25 37 90			2	25 37 90	4	4	12.829			pk-L	12.829
3-5	12 01 10			3	12 01 10	5	4	189.512			pk-L	189.512
3-6	12 12 28			3	12 12 28	6	4	128.882			pk-L	128.882
3-7	12 42 21			3	12 42 21	7	4	68.390			pk-L	68.390
3-8	12 51 51			3	12 51 51	8	4	58.301			pk-L	58.301
2	285 085	105 085	193 010	1	193 010	9	4	78.506				78.506
1												
9	193 010	13 01 07										
	GR3 pkL											
2	Sipat Di Atas	27 59 27		1	27 59 27	10	4	92.236				92.236
1												
10	27 59 27	209 59 27										
	pkB pk-L GR4											
10-11	9 01 21			10	9 01 21	11	4	89.787			pkL GR-5	89.787
10-12	15 41 06			10	15 41 06	12	4	88.315			pkL 78M/19	88.315
10-13	358 202			10	358 202	13	4	99.586			pk-L	99.586

Rajah di muka

[illegible]

