

No. Fail J2272 Wangsa 9

Rajah di muka

Stesen	BEARING / SUDUT			Dari Stn.	GARISAN		Ke Stn.	Sudut Pugak ($\pm$)	Jarak	Suhu	Jarak Antara Tupang	Jarak Mukamat
	Penyilang Kiri	Penyilang Kanan	Purata		Bearing Mukamat							
	Datum	Daripada		2	329 19 11	pk.B	1	4	32.915	10/9/15		32.915
1	329 19 11	199 19 11	90 25 36	2	90 25 36	pk.B	3	4	135.723			135.723
2	3	90 25 36	270 25 36									
	pk.B											
2-4	5 38 56			2	5 38 56		4	4	57.160		pk.L ←	57.160
2-5	99 55 33			2	99 55 33		5	4	18.065		pk.L ←	18.065
2-6	89 28 09			2	89 28 09		6	4	28.157		pk.L ←	28.157
1-7	0 47 30			1	0 47 30		7	4	117.950		BKL	117.950
2-8	105 01 19			2	105 01 19		8	4	63.261		pk.L (RM) 1	63.261
3-9	73 59 18			3	73 59 18		9	4	12.917		pk.L (RM) 2	12.917
3-10	88 30 47			3	88 30 47		10	4	70.897		pk.L (RM) 3	70.897
3-11	75 18 31			3	75 18 31		11	4	55.298		pk.L ←	55.298
2	270 25 36	90 25 36	68 55 19	3	68 55 19		12	4	99.775			99.775
3	12	68 55 19	278 55 19									
	pk.B											
3	278 55 19	68 55 19	53 03 52	12	53 03 52		13	4	79.035			79.035
12	13	53 03 52	233 03 52									
	pk.B											
12-14	277 33 07			12	277 33 07		14	4	50.226		pk.L ←	50.226
12-15	301 11 29			12	301 11 29		15	4	32.626		pk.L ←	32.626
13-16	56 12 53			13	56 12 53		16	4	3.185		pk.L (RM) 4	3.185
13-17	5 46 06			13	5 46 06		17	4	36.987		pk.L (RM) 5	36.987

No. Fail

Rajah di muka

[illegible]

COORDINATE FROM JURUKUR MAKMUR CASSINI COORDINATE

Given by
Surveyor Akbar.

