

No. Fail

Rajah di muka

Stesen	BEARING / SUDUT			Dari Stn	GARISAN		Ke Stn	Sudut Pukak (°)	Jarak	Suhu	Jarak Antara Tupang	Jarak Mukamat
	Penyangk kiri	Penyangk Kanan	Purata		Bearing Mukamat							
17	399 57 49	169 57 49	157 23 53	18	157 23 53		19	4	33.310			33.310
18												
19	157 23 53	337 23 53										
	pht.											
18	337 23 53	157 23 53	176 40 19	19	176 40 19		4	4	32.129			32.129
19												
4	176 40 19	356 40 19										
	pht.											
19	356 40 19	176 40 19	106 37 36	4	106 37 36		3		Silva Lekat m/s / Ruang 3			
4												
3	106 37 36	286 37 36										
	Bering 43 Diberan 106 37 36											
	Sipatitnya Diberan 106 37 36											
	Tilakan Ni)											
	Pembetulan Ni)											
2	70 19 51	250 19 51	357 50 57	1	357 50 57		30	4	219.379	21/10/15		219.379
1												
30	357 50 57	117 50 57										
	pht.											
1-31	39 22 20			1	39 22 20		31	4	32.890		RCL	32.890
1-32	299 03 52			1	299 03 52		32	4	28.076		PB	28.076
30-33	236 42 09			30	236 42 09		33	4	15.593		PB	15.593
30-37	85 30 11			30	85 30 11		37	4	19.109		PB	19.109