

No. Fail J2131 CHD Plot 133

Rajah di muka _____

Stesen	BEARING / SUDUT			Dari Stn.	GARISAN		Ke Stn.	Sudut Pukak ($\pm$)	Jarak	Suhu	Jarak Antara Tupang	Jarak Mukamat
	Penyilang Kiri	Penyilang Kanan	Purata		Bearing Mukamat							
	Datum Daripada			200	283 51 19	37	H		39.328	21/12/15		39.328
				stn			stn					
				lamb			lamb					
				pts 2000			(mukamat)					
							(garisan)					
200	37	283 51 19	103 51 19	339 19 37	200	339 19 37	50	H	38.827			38.827
	50	339 19 37	159 19 37									
	pkx											
50-51	0 00 00			50	0 00 00	51	H	9.500		pkx		9.500
50-52	90 00 00			50	90 00 00	52	H	8.275		pkx		8.275
50-53	90 00 00			50	90 00 00	53	H	18.275		pkx		18.275
50-59	125 25 35			50	125 25 35	59	H	22.927		pkx		22.927
50-60	0 00 00			50	0 00 00	60	H	11.939		pk.B (RM)		11.939
50-61	180 00 00			50	180 00 00	61	H	10.825		pk.B (RM)		10.825
50-62	270 00 00			50	270 00 00	62	H	2.696		pk.B (RM)		2.696
50-63	90 00 00			50	90 00 00	63	H	21.051		pk.B (RM)		21.051
51-64	270 00 00			51	270 00 00	64	H	3.135		pk.B (RM)		3.135
51-65	90 00 00			51	90 00 00	65	H	20.776		pk.B (RM)		20.776
52-66	0 00 00			52	0 00 00	66	H	10.826		pk.B (RM)		10.826
52-67	180 00 00			52	180 00 00	67	H	10.993		pk.B (RM)		10.993
53-68	0 00 00			53	0 00 00	68	H	10.566		pk.B (RM)		10.566
53-69	180 00 00			53	180 00 00	69	H	11.122		pk.B (RM)		11.122
59-70	270 00 00			59	270 00 00	70	H	20.797		pk.B (RM)		20.797
59-71	90 00 00			59	90 00 00	71	H	2.979		pk.B (RM)		2.979

