

No. Fail Wangsa 9 Setting Out LVL 5 (31.10.2015)

Rajah di muka

Stesen	BEARING / SUDUT			Dari Stn.	GARISAN		Ke Stn.	Sudut Pukak ($\pm$)	Jarak	Suhu	Jarak Antara Tupang	Jarak Mukamat
	Penyilang Kiri	Penyilang Kanan	Purata		Bearing Mukamat							
12	233 03 52	53 03 52	309 16 27	13	309 16 27	50	4	4	92.550			92.550
13												
50	309 16 27	129 16 27										
	pk.B											
50-51	233 59 50			50	233 59 50	51	4	4	31.150	pk.B (RM)		31.150
50-52	233 59 50			50	233 59 50	52	4	4	19.750	pk.B (RM)		19.750
50-53	233 59 50			50	233 59 50	53	4	4	32.000	pk.B (RM)		32.000
50-57	233 59 50			50	233 59 50	57	4	4	16.700	pk.B (RM)		16.700
59-55	233 59 50			59	233 59 50	55	4	4	31.150	pk.B (RM)		31.150
59-56	233 59 50			59	233 59 50	56	4	4	19.750	pk.B (RM)		19.750
53-57	233 59 50			53	233 59 50	57	4	4	31.150	pk.B (RM)		31.150
53-58	233 59 50			53	233 59 50	58	4	4	19.750	pk.B (RM)		19.750