

No. 1411 JR 422 Bukit Beruntung Golf

Rajesh di muka

	Daerah	Desa	RT	RW	Desa	RT	RW	Desa	RT	RW
Datum Daripada	2 89 49 01	1	4	178 892	178 892					
	pkB	Aj	At	pkB						
	Ag	6/25								
1 89 49 01	2 89 49 01	2 89 49 17	2 2 89 49 17	3	4	85 016	85 016			
3 2 89 49 17	89 49 17									
pkB										
1 Sepati	At	33 18 01	2 33 18 01	4	4	81 251	81 251			
7 33 18 01	2 33 18 01									
pkB										
2-5	2 291 25 02	5	4	19.568	pkL	19.568				
2-6	2 120 58 96	6	4	16.680	pkL	16.680				
2-7	2 99 53 30	7	4	95.523	pkL	95.523				
2-8	2 95 11 16	8	4	77.627	pkL	77.627				
2-9	2 89 03 28	9	4	79.653	BKL	79.653				
2-10	2 78 46 09	10	4	36.983	BKL	36.983				
2-11	2 27 44 47	11	4	7.230	BKL	7.230				
4-12	4 15 28 47	12	4	11.947	BKL	11.947				
4-13	4 312 27 35	13	4	15.850	BKL	15.850				
4-14	4 288 09 07	14	4	31.290	BKL	31.290				

No. Fail.

BEARING & DIST

ARIPAN

Diagrama Teknik

Stesen

Penyulang Kiri

Penyulang Kanan

Tinggi

Dist

km

Bearing Magnetic

Alt

m

South Magnetic

True

Angle

Dist

km

DAERAH HUKU SELANGOR
BANDAR SEREMBAN
SEKSYEN 20
TANPA SKALA

