

No. Fail JR 272 Wayan 9 Block A Cml 8

Stesen	BEARING / SUBUT			Jarak km	Jumlah Bearing Mutiara	Kp km	Rajah / Benda		Jarak km	Jumlah Bearing Mutiara
	Penyilang Kiri	Penyilang Kanan	Barata				1st	2nd		
	Detran Daripada			12	53 03 52	13	4	79.035	79.035	5/9/19
13	53 03 52	233 03 52	278 55 35	12	278 55 35	50	4	99.772	99.772	
50	278 55 35	08 55 35								
	pk.B (00/1002)									
12	08 55 35	278 55 35	277 53 95	50	277 53 95	51	4	108.531	108.531	
50	277 53 95	97 53 95								
	pk.B									
50	97 53 95	277 53 95	350 72 02	51	350 72 02	52	4	70.633	70.633	
51	350 72 02	170 72 02								
	pk.B									
51	170 72 02	350 72 02	75 36 18	52	75 36 18	53	4	13.171	13.171	
52	75 36 18	255 36 18								
	pk.B (RM)									
53-54	255 35 50	9.670	pk.B (RM)							
53-55	375 35 50	13.775	pk.B (RM)							
53-56	165 35 50	21.220	pk.B (RM)							