

No. Fail *JZ 458 Jln Dasar*

Rajah di muka

Stesen	BEARING / SUDUT			Dari Stn.	GARISAN		Ke Stn.	Sudut Pugak (±)	Jarak	Subu	Jarak Antara Tupang	Jarak Mukamat
	Penyilang Kiri	Penyilang Kanan	Purata		Bearing Mukamat							
	Datun Dapoda			2	353 1955		1	H	53.737	10/5/19		53.737
					Ag Ak.							
					Dgn MH							
2-3	257 5711			2	257 5711		3	H	25.992		pk.CE	25.992
2-4	255 5627			2	255 5627		4	H	11.696		pk.CE	11.696
2-5	333 3330			2	333 3330		5	H	21.813		pk.CE	21.813
1	2	173 1955	353 1955	325 3329	1	325 3329	6	H	53.219			53.219
6	325 3329	195 3329										
	pk.B											
6	1	195 3329	325 3329	237 5133	6	237 5133	7	H	75.238			75.238
	7	237 5133	57 5133									
	pk.B											
7	6	57 5133	237 5133	139 9610	7	139 9610	8	H	29.205			29.205
	8	139 9610	319 9610									
	pk.B											
7-9	321 9206			7	321 9206		9	H	9.038		pk.LE	9.038
8-10	283 9921			8	283 9921		10	H	37.183		pk.CE	37.183
8-11	162 9537			8	162 9537		11	H	18.999		BKL	18.999
8-17	161 3119			8	161 3119		11	H	13.327		BKL	13.327
	Demarate.											
8-12	162 3602	19.082	pk.B									
8-13	158 3503	7.613	pk.B									
1-17	285 3356	19.613	pk.B									
1-15	265 4819	19.703	pk.B									
1-16	276 4349	13.010	pk.B									
1-17	225 2111	14.154	pk.B									

[illegible]

ST/1 Pads

[illegible]