

No. Fail JE 505 Jln Kota.

Rajah di muka

No. Fail J2 505 01m 20m.												
Stesen	BEARING / SUDUT			Dari Stn.	GARISAN		Ke Stn.	Sudut Pukak ($\pm$)	Jarak	Suhu	Jarak Antara Tupang	Jarak Mukamat
	Penyilang Kiri	Penyilang Kanan	Purata		Bearing Mukamat							
	Dataran Daripada 6/15.			2	256 29 26	1	4	75.686				75.686
					Ag At. Dgn GAS							
1	256 29 26	76 29 26	89 13 21	2	99 13 21	3	4	70.201				70.201
2												
3	99 13 21	279 13 21										
	pk.B											
1	Seperti Di Atas			2	261 99 06	4	4	36.173				36.173
2												
4	261 99 06	81 99 06										
	pk.B											
1-5	52 12 22			1	52 12 22	5	4	11.990			pk.L	11.990
1-6	239 09 31			1	239 09 31	6	4	37.318			pk.L	37.318
1-7	269 47 93			1	269 47 93	7	4	70.991			pk.L	70.991
2	279 13 21	99 13 21	0 32 98	3	0 32 98	8	4	199.169				199.169
3												
8	0 32 98	180 32 98										
	pk.B											
2	Seperti Di Atas			3	92 16 21	9	4	117.002				117.002
3												
9	92 16 21	272 16 21										
	pk.B											
9-10	50 29 57			9	50 29 57	10	4	10.888			SL	10.888
9-11	18 19 10			9	18 19 10	11	4	12.315			SL	12.315
8-12	351 93 20			8	351 93 20	12	4	63.706			pk.L	63.706

