

No. Fail JZ 536 Garing Heights Jln

No. Fail

Rajah di muka

Stesen	BEARING / SUDUT			Dari Stn.	GARISAN	Ke Stn.	Sudut Pukak (±)	Jarak	Suhu	Jarak Antara Tupang	Jarak Mukamat
	Penyilang Kiri	Penyilang Kanan	Purata		Bearing Mukamat						
	Daruyan	Daripada		1	183 5525	2	4	39.856			39.856
					A3 At.						
					A3 1 MY						
2	183 5525	323 5525	286 0786	1	286 0786	3	4	75.163			75.163
3	286 0786	86 0786									
	pk.B										
1-4	106 5780			1	106 5780	4	4	15.82		BKL	15.82
3-5	385 2536			3	385 2536	5	4	7.723		BKL	7.723
3-6	198 1622			3	198 1622	6	4	36.881		BKL	36.881
3-7	178 3233			3	178 3233	7	4	16.721		BKL	16.721
3-8	132 1337			3	132 1337	8	4	9.783		BKL	9.783
2-9	22 0517			2	22 0517	9	4	8.865		BKL	8.865
2-10	55 3809			2	55 3809	10	4	11.609		BKL	11.609
2-11	95 7903			2	95 7903	11	4	18.711		SPL	18.711
1	323 5525	183 5525	251 2905	2	251 2905	12	4	21.337			21.337
12	251 2905	71 2905									
	pk.B.										
12-13	81 5902			12	81 5902	13	4	16.687		PL	16.687
12-14	22 1698			12	22 1698	14	4	19.787		BKL	19.787
12-15	285 9202			12	285 9202	15	4	16.008		PL	16.008
12-17	203 0922			12	203 0922	17	4	13.117		PB	13.117
2-16	65 1870			2	65 1870	16	4	52.379		pk.B	52.379

Rajah di muka

[illegible]