

JE 917 Sri Bintang.

Rajah di muka

Stesen	BEARING / SUDUT			Dari Stn.	GARISAN	Ke Stn.	Sudut Pagak (±)	Jarak	Suhu	Jarak Antara Tumpang	Jarak Mukhtamat
	Penyilang Kiri	Penyilang Kanan	Purata		Bearing Mukhtamat						
	Datum	Sampah	99 78 53	30	99 78 53	3	/	36.090	6/5/21		36.090
			pkB		pkC						
			TBM A		Sh tams						
30	99 78 53	279 78 53	37 59 43	30	37 59 43	2	/	50.807			50.807
	2 37 59 43	27 59 43			pkC						
					sh tams						
30-31	31/ 1933			30 31/ 1933	31	/		37.759		pk.CE	37.759
30-32	10/ 7330			30 10/ 7330	32	/		52.900		pk.CE	52.900
30-33	102 0900			30 102 0900	33	/		57.910		pk.CE	57.910
31-37	353 1613			30 353 1613	37	/		13.037		pk.CE	13.037
30-35	25 5319			30 25 5319	35	/		23.810		pk.CE	23.810
31-36	283 5016			31 283 5016	36	/		18.193		pk.CE	18.193
Setting Out RM & TBM.											
30-70	379 0113			30 379 0113	70	/		11.862		pk.B (RM)	11.862
30-71	28 5838			30 28 5838	71	/		20.019		pk.B (RM)	20.019
31-72	275 2037			31 275 2037	72	/		16.177		pk.B (RM)	16.177
31-73	178 0009			31 178 0009	73	/		17.797		pk.B (RM)	17.797
31-77	250 0959			31 250 0959	77	/		17.097		pk.B TBM F	17.097

Rajah di muka .

[illegible]

