

No. Fail J2917 Sri Bintang.

Rajah di muka

Stesen	BEARING / SUDUT			Dari Stn.	GARISAN		Ke Stn.	Sudut Pukak (+)	Jarak	Suhu	Jarak Antara Tupang	Jarak Mukamat
	Penyilang Kiri	Penyilang Kanan	Purata		Bearing Mukamat							
○	Datum	Daripada	99 78 53	30	99 78 53	3	4	36.090	6/5/21			38.090
			pkB		pkC							
			7BM F		Stn							
					1km							
30	99 78 53	279 78 53	37 57 43	30	37 57 43	2	4	50.807				50.807
30	2	37 57 43	27 57 43		pkC							
					Stn							
					1km							
30-31	31/1933			30	31/1933	31	4	37.759			pk.CE	37.759
30-32	10/7330			30	10/7330	32	4	52.900			pk.CE	52.900
30-33	102 08 00			30	102 08 00	33	4	57.910			pk.CE	57.910
30-34	353 16 13			30	353 16 13	34	4	13.037			pk.CE	13.037
30-35	25 53 19			30	25 53 19	35	4	23.810			pk.CE	23.810
30-36	283 50 18			30	283 50 18	36	4	18.193			pk.CE	18.193
	Setting Out RM & 7BM.											
30-70	379 01 13			30	379 01 13	70	4	11.862			pk.B (RM)	11.862
30-71	28 58 38			30	28 58 38	71	4	20.019			pk.B (RM)	20.019
30-72	275 20 37			30	275 20 37	72	4	16.177			pk.B (RM)	16.177
30-73	198 00 09			30	198 00 09	73	4	19.999			pk.B (RM)	19.999
30-74	250 09 59			30	250 09 59	74	4	19.099			pk.B 7BM	19.099
											F	
30-71	28 58 38			30	28 58 38	71	4	20.019			pk.B (RM)	20.019
○												

Purpose

78M 456
Hui Level: 88.660
JR471 Level: 88.662
0.022