

No. Fail JE 58/ Jln Beka

Rajah di muka

Stesen	BEARING / SUDUT			Dari Stn.	GARISAN		Ke Stn.	Sudut Pukak (±)	Jarak	Suhu	Jarak Antara Tupang	Jarak Muktamat
	Penyilang Kiri	Penyilang Kanan	Purata		Bearing Muktamat							
○	Datum Daripada			2	131 18 18 Ag Ak. Dgn MH		1	4	23.088			23.088
1	2	311 18 18	131 18 18	13 32 29	1	13 32 29	3	4	23.267			23.267
	3	13 32 29	123 32 29									
		BKL										
2	1	131 18 18	311 18 18	31 58 01	2	31 58 01	4	4	21.229			21.229
	4	31 58 01	21 58 01									
		pk.										
2	1	Seperti Di Atas	375 08 13		2	375 08 13	5	4	183.006			183.006
	5	375 08 13	165 08 13									
		pk.B										
5	2	165 08 13	375 08 13	333 78 28	5	333 78 28	6	4	107.115			107.115
	6	333 78 28	153 78 28									
		pk.B										
5-7		158 08 55		5	158 08 55	7	4	75.787			BKL	75.787
6-8		130 59		6	130 59	8	4	7.163			BKL	7.163
7-9		55 31 10		7	55 31 10	9	4	23.070			PL	23.070
7-10		108 76 89		7	108 76 89	10	4	15.589			pk.B	15.589
2-11		107 72 71		2	107 72 71	11	4	11.871			pk.B	11.871
2-12		39 07 76		2	39 07 76	12	4	8.983			pk.B	8.983
2-13		356 72 83		2	356 72 83	13	4	22.972			pk.B	22.972
2-14		351 70 57		2	351 70 57	14	4	35.257			pk.B	35.257
7-15		22 58 78		7	22 58 78	15	4	77.500			pk.B	77.500
7-16		30 72 07		7	30 72 07	16	4	36.665			pk.B	36.665

24

Purpose

[illegible]