

No. Fail J7607 Laby Bridge.

Rajah di muka.....

No. Fail												
Stesen	BEARING / SUDUT			Dari Stn.	GARISAN	Ke Stn.	Sudut Pukak (±)	Jarak	Suhu	Jarak Antara Tumpang	Jarak Mukamat	
	Penyilang Kiri	Penyilang Kanan	Purata		Bearing Mukamat							
	Darym Daripada			27	159 56 50	23	H	51.350	18/11/21		51.350	
				ptk		ptk						
23	159 56 50	339 56 50	371 40 00	27	371 40 00	25	H	27.215			27.215	
25	371 40 00	161 40 00										
	ptk											
23	168 26 00	168 26 00	27	168 26 00	26	H	26.608				26.608	
26	168 26 00	378 26 00										
	TBM JMI											
23	0 46 02	0 46 02	27	0 46 02	27	H	109.999				109.999	
27	0 46 02	180 46 02										
	ptk											
27	180 46 02	0 46 02	300 16 07	27	300 16 07	28	H	102.162			102.162	
28	300 16 07	120 16 07										
	ptk											
27	120 16 07	300 16 07	49 30 26	28	49 30 26	29	H	77.157			77.157	
29	49 30 26	229 30 26										
	ptk											
29-30	49 30 26			29	49 30 26	30	H					
28-30	290 49 26			28	290 49 26	30	H	18.515		BKL	18.515	
29-31	277 36 51			29	277 36 51	31	H	193.937		BKL	193.937	
29-32	269 09 20			29	269 09 20	32	H	153.915		ptk	153.915	
29-33	285 41 42	* (sump bar)		29	285 41 42	33	H	85.657		ptk.B	85.657	
29-34	262 59 59	* (banuh jambatan)		29	262 59 59	34	H	18.450		ptk	18.450	
29-35	103 39 30			29	103 39 30	35	H	22.203		BKL	22.203	