


No. Fail

J2611 Setra Bukit

Rajah di muka

Stesen	BEARING / SUDUT			Dari Stn.	GARISAN		Ke Stn.	Sudut Pugak (±)	Jarak	Suhu	Jarak Antara Tupang	Jarak Mukamat
	Penyilang Kiri	Penyilang Kanan	Purata		Bearing Mukamat							
○	Datum	Daripada		↗	330 29 53	1	H	57.389	12/1/22		57.389	
				pkB	Ag Ak.	pkB						
					Dgn 925.							
1	330 29 53	150 29 53	286 53 13	↗	286 53 13	3	H	30.997			30.997	
②												
3	286 53 13	286 53 13										
	pkB											
1	Sperti Di Atas	57 39 39	↗	57 39 39	7	H	78.116				78.116	
②												
7	57 39 39	237 39 39										
	pkB											
↗	237 39 39	57 39 39	155 17 18	↗	155 17 18	5	H	17.117			17.117	
④												
5	155 17 18	335 17 18										
	pkB											
7	335 17 18	155 17 18	293 19 40	↗	293 19 40	3	H	18.882			18.882	
⑤												
3	293 19 40	63 19 40										
5	63 19 40	293 19 40	286 53 13	↗	286 53 13	2	Sila Lihat R2					
③	286	286	286		Berang							
↗	286 53 13	286 53 13			Tutup.							
5-6	76 46 20			5	76 46 20	6	H	9.189		pkL	9.189	
5-7	29 43 39			5	29 43 39	7	H	11.007		pkB	11.007	
4-8	71 30 12			7	71 30 12	8	H	9.706		pkB	9.706	
2-9	105 40 40			2	105 40 40	9	H	20.512		pk.B	20.512	
2-10	46 00 47			2	46 00 47	10	H	14.949		pkL	14.949	
2-11	0 01 50			2	0 01 50	11	H	29.390		BKL	29.390	

J261/ Setia Bakti 2



Location ✓✓✓ ✓✓✓ ✓✓✓ ✓✓✓ ✓✓✓ ✓✓✓

Purpose

[illegible]