

No. Fail

J2675 Sri Gembak.

Rajah di muka

No. Fail												
Stesen	BEARING / SUDUT			Dari Stn.	GARISAN	Ke Stn.	Sudut Pugak (±)	Jarak	Suhu	Jarak Antara Tupang	Jarak Muktamat	
	Penyilang Kiri	Penyilang Kanan	Purata		Bearing Muktamat							
2	211 59 51	Datum		1	0 29 17	2	4	58.390			58.390	
6	Daripada			pkB	A3 Bt.	pkB						
					Dgn GRS							
2	0 29 17	180 29 17	103.3659	1	103.3659	3	4	48.268			48.268	
3	103.3659	283.3659										
	pkB											
1	283.3659	103.3659	6 57 26	3	6 57 26	4	4	33.590			33.590	
4	6 57 26	186 57 26										
	pkB											
1	Sipendi Di Atas	186 49 37	3	186 49 37	5	4	50.999				50.999	
5	186 49 37	6 49 37										
	pkB											
3	6 49 37	186 49 37	97 23 49	5	97 23 49	6	4	37.359			37.359	
6	97 23 49	277 23 49										
	pkB											
5	277 23 49	97 23 49	7 59 11	6	7 59 11	7	4	197.775			197.775	
7	7 59 11	187 59 11										
	pkB											
6-8	263.3931			6	263.3931	8	4	9.693		BFL	9.693	
6-9	132.2741			6	132.2741	9	4	6.711		SPL	6.711	
7-10	93.4428			7	93.4428	10	4	9.787		SPL	9.787	

J8672 Sri Gombak.

1.2775		57.373	TBM F3212
	1.2951	57.3559	F2
1.5673	1.4760	57.1795	F1
	1.3894	57.3524	F3
	0.9932	57.7986	F4
	0.7591	57.987	TBM F3213

BM BG1095

GPS Level: 56.989

BM Level: 57.069

0.085

TBM F3212

GPS Level: 57.288

0.085

57.373

