

No. Fail J2700 Putra Murni

Rajah di muka

Stesen	BEARING / SUDUT			Dari Stn.	GARISAN		Ke Stn.	Sudut Pukak (±)	Jarak	Suhu	Jarak Antara Pupang	Jarak Muktamam
	Penyilang Kiri	Penyilang Kanan	Purata		Bearing Muktamam							
	Datum Darigada			1	109 49 27	A3 Ak. Dgn MY	2	4	57.322			57.322
1	2	109 49 27	289 49 27	16 07 52	1	16 07 52	3	4	96.025			96.025
	3	16 07 52	196 07 52									
		pkB										
	1-4	192 29 85		1	192 29 85		4	4	28.089		pkLE	28.089
	1-5	1 26 52		1	1 26 52		5	4	25.778		pkLE	25.778
	3-6	210 49 09		3	210 49 09		6	4	28.853		pkLE	28.853
	3-7	20 59 19		3	20 59 19		7	4	16.086		pkLE	16.086

JZ 700 Dutra Murni

1.3376

29.779

GPS 1

1.3531

29.7285

TBM F9105

1.4532

29.6289

F1009

1.3989

29.6827

F1005

1.4942

29.5879

TBM F9100/P2

BM 62067

GPS Level: 17.897

BM Level: 17.791

0.106

GPS 1

GPS Level: 29.850

- 0.106

29.744