



landsurvey88 landsurvey88 <weikaiy@gmail.com>

Re: Trillion Site - Stn 11 as base

3 messages

Heng Wei Kaiy <weikaiy@gmail.com>

Thu, Dec 22, 2011 at 1:04 AM

To: FS' Mr Foo Chee Yong <foocomp@yahoo.com>

Cc: Heng Wei Kaiy <weikaiy@gmail.com>

Dear Bro Foo,

Please find attached the calculation of survey base line in 2 pages for your perusal.

Base : stn 11-1, 11-10, 11-3, 11-7. Hence, please use stn 11 picked up by you as survey base.

Please find attached the autocad drawing using stn 11 as base for your perusal and further action. (After using stn 11 as base, we noticed that RM 3 (Sunway) in the attached softcopy is very close (3mm) to the RM you have picked up at site.

Hence, please carry-out the grid line setting-out survey at site basing on stn 11 as base.

Please pick up TBM F1983 and TBM F1984 to show in the survey plan.

Thank you.

best regards,
Heng

3 attachments **Survey Base - Stn 11 - pg2.jpg**
1492K **Survey Base-Stn 11.jpg**
2709K **JZ_11_WP_26_S_2.dwg**
177K

Heng Wei Kaiy <weikaiy@gmail.com>

Sun, Dec 25, 2011 at 3:32 PM

To: FS' Mr Foo Chee Yong <foocomp@yahoo.com>

Cc: Heng Wei Kaiy <weikaiy@gmail.com>

Dear Bro Foo,

As discussed, please help to do the following survey works at Trillion site on this coming Monday, 26-12-2011:

1.0) Demarcation survey on Lot 919.

1.1) Please use stn 11-10 as base (+ 2' 16" in bearing and factoring of 0.9998126974 (117.435 / 117.457))

1.2) Please do PO & New Adjustment by applying + 2' 16" on the CP bearing and factoring of 0.9998126974 on the CP distance of south western, western and northern and north eastern boundary of Lot 919.

2.0) Grid Line Setting-out Survey

2.1) Please do the grid line setting-out survey based on stn 11 as mentioned in our email to you dated Thu, Dec

22, 2011 at 1:04 AM as below.

Thank you.

best regards,
Heng

[Quoted text hidden]

3 attachments



Survey Base - Stn 11 - pg2.jpg

1492K



Survey Base-Stn 11.jpg

2709K



JZ_11_WP_26_S_2.dwg

177K

Heng Wei Kaiy <weikaiy@gmail.com>
To: FS' Mr Foo Chee Yong <foocomp@yahoo.com>
Cc: Heng Wei Kaiy <weikaiy@gmail.com>

Sun, Jan 8, 2012 at 6:05 PM

Dear Bro Foo,

Boundary Demarcation Survey at Trillion Site:

Further to our telephone conversation today, please help to do the following work at Trillion Site:

- 1) To push the BKL of stn 22 / stn 40 into the correct position. (I will show it as BKL in the survey plan.)
- 2) To destroy PKL of stn 21 which is out of position (I will show it as HWP in the survey plan)
- 3) Please plant RM for Stn 44 & Stn 45 (which you named them as TT ealier.) As discussed, RM doesn't mean must be very close to the stn. It can be 5m, 10m, 15m, etc...as long as client can refer to it while working at site.

In future, demarcation survey must be planted with iron pipe or nail in concrete if old boundary marks could not be found at site. In Town area, if the old boundary stone is out of its position for more than 5 cm, we must push it into its original position (with the condition of good base found and to apply PO & New adjustment method on the boundary line).

Do inform me by email after you have done the above mentioned work at site. In future, please try to send all the emails to my email address: weikaiy@gmail.com

Should you require further information or clarification, please do not hesitate to contact us.

Thank you.

best regards,
Heng Wei Kaiy

[Quoted text hidden]