

No. Fail 650 195 Jijang Si Utara Titik.

Rajah di muka

Stesen	BEARING / SUDUT			Dari Stn.	GARISAN		Ke Stn.	Sudut Pukak (±)	Jarak	Suhu 4/2/09	Jarak Antara Tupang	Jarak Mukamat
	Penyilang Kiri	Penyilang Kanan	Purata		Bearing	Mukamat						
	Notam Daripada PA 1005009			2	102588	1	4		31.110			31.110
					pk.B							
1	102588	282588	1901020	2	1901020	3	4		5.899			5.899
2												
3	1901020	101020										
					pk.L							
1	Seperti Di Atas	2555320	2	2555320	9	4			20.801			20.801
2												
9	2555320	755320										
					pk.L							
1	Seperti Di Atas	772796	2	772796	5	4			33.625			33.625
2												
5	772796	2572796										
					pk.B							
1	Seperti Di Atas	2722328	2	2722328	6	4			39.631			39.631
2												
6	2722328	922328										
					pk.B							
2	2572796	772796	1921638	5	1921638	7	4		76.281			76.281
5												
7	1921638	121638										
					pk.B							
5	121638	1921638	2735939	7	2735939	8	4		36.633			36.633
7												
8	2735939	335939										
					pk.B							

No. Fail

Rajah di muka

Stesen

Penyilang Kiri

BEARING / SUDUT

Penyilang Kanan

Purata

Dari

Stn.

GARISAN

Bearing Muktamat

Ke

Stn.

Sudut Pugak
(±)

Jarak

Suhu

Jarak
Antara
Tupang

Jarak Muktamat

pk. B
16

95 30 28 91.882

99.856

22 11 1

13

pk. B

21 99 13 93.26

Rajah di muka

[illegible]

WILAYAH KERSEKUTUAN LUACA CUMPAH
MUKAM BAYU

