

No. Fail TRJ 8/88 Kuala Selangor (Jesco)

Raiah di muka

Stesen	BEARING / SUDUT			Dari Stn.	GARISAN	Ke Stn.	Sudut Pukak (°)	Jarak	Suhu	Jarak Antara Tiang	Jarak Mukamat
	Penyilang Kiri	Penyilang Kanan	Purata		Bearing Mukamat						
	180 088	320 088	298 1158	2	180 088	1	4	197.885	17/3/2012		197.885
	298 1158	118 1158		3	298 1158	3	4	10237			10237
	230 1256	50 1256		7	230 1256	7	4	197.375			197.375
	50 1256	230 1256	222 0178	7	222 0178	5	4	71.029			71.029
	222 0178	72 0178		5	222 0178	5	4	18.033		BL	18.033
	320 9157			5	320 9157	7	4	25.719		BL	25.719
	129 2850			5	129 2850	8	4	37.900		PL	37.900

Tarikh *Kuch Selayon* Aras

Dibuat untuk

14

Daripada *781 8189*

Ke

Pandangan Belakang	Pandangan Antara	Pandangan Hadapan	Naik	Turun	Aras Yang Dilaras	Jarak	Catitan
1.958	1.682	1.880			2.506	781 81	
	1.880	1.880			2.989	8M 8 5085	RC: 2.506m
1.513	1.796	1.388	1.882		3.116	1.7004 83	
		1.858	1.738		3.171	781 82128	Aku knd.
						781 82129	/ 1.1009 / 1.12