

No. Fail LOT 29526, 2632, 2129 SIKAMAT

Rajah di muka

Stesen	BEARING / SUDUT			Dari Stn.	GARISAN		Ke Stn.	Sudut Pukak (±)	Jarak	Suhu	Jarak Antara Tupang	Jarak Mukamat
	Penyilang Kiri	Penyilang Kanan	Purata		Bearing Mukamat							
	BERING	ANDAIAN	345 00 00	2	344 28 55	1	H	570.309			+13.074	570.309
			M-31 05	1481		1561						
				PXB		PXB	H	570.311			-13.012	
			344 28 55	1595		1596					R1: 98.631	
1	345 00 00	65 00 00	76 10 20	2	75 39 15	3	H	284.230			+13.809	284.230
2			M-31 05	1481		1596						
3	76 10 20	256 10 20										
	PXB		75 39 15								R1: 89.322	
1	S. D. A.	26 23 05	2	25 52 00	4	H	76.688				+5.839	76.688
3	R1: 85.628	M-31 05	1481	BERING	1544							
4	26 23 05	206 23 05		4	DGN MH	2	H	76.688			-5.842	
	PXB			1544		1471					R1: 91.402	
2	206 23 05	26 23 05	127 18 05	4	126 47 00	5	H	6.504			+1.347	6.504
4			M-31 05	1541		1336						
5	127 18 05	307 18 05										
	PL		126 47 00									
2	S. D. A.	137 56 55	4	137 25 50	6	H	6.701				+0.813	6.701
4			M-31 05	1541		1338						
6	137 56 55	317 56 55										
	PL		137 25 50									
2	S. D. A.	349 34 30	4	349 03 25	7	H	4.876				+1.284	4.876
4			M-31 05	1541		1335						
7	349 34 30	169 34 30										
	PL		349 03 25									
2	S. D. A.	56 44 25	4	56 13 20	8	H	30.465				+5.708	30.465
4			M-31 05	1541		1551						
8	56 44 25	236 44 25		8		4	H	30.463			-5.684	
	PXB		56 13 20	1561		1573					R1: 97.099	