



Surmap Sdn. Bhd. (158873-H)

81A, Jalan SS 15/4B, 47500 Subang Jaya, Selangor.

Tel: 03-5633 8877, 5633 8873 & 5633 8470

Fax: 03-5634 0509



Quotation No.: 100129

Date: 13-06-2012

Geo Technic Surveys and Mapping

No. 21, Jalan Putra Permai 10/2J,

Seksyen 10, Putra Height,

47650 Subang Jaya

Attn : Mr. Foo Chee Yong (h/p: 012-281 9844)

Dear Sir

QUOTATION FOR SURVEYING INSTRUMENTS AND ACCESSORIES

We thank you for the invitation to quote for the above and are pleased to submit herewith our proposal for your kind consideration.

Item	Description	QTY	Unit Price (RM)	Total Price (RM)
1	Repair of Leica TCR705 Total Station S/N: 651414 Problem: Accident Unit, cannot power on. Part-replacement:- ❖ Horizontal End-Coder Disc ❖ Gris for the Horizontal Clamp ❖ Verticle Endcorder Disc ❖ Gris for the Verticle Clamp ❖ Fiber Optic Cable ❖ Electronic Compensator ❖ Horizontal Clamp  Workmanship Chargers NOTE: The equipment is dented and seriously damage by strong impact. We suspect the equipment is dropped and dented caused the compensator, End-coder Disc, Gris for Horizontal and Verticle clamp jams.  Fibre Optic Cable Electric Shock  Horizontal End-coder Disc Broken  Compensator Board Unstable	1unit 1unit 1unit 1unit 1set 1unit 1unit 1x	6,700.00 450.00 6,700.00 450.00 1,800.00 7,500.00 2,200.00 500.00	6,700.00 450.00 6,700.00 450.00 1,800.00 7,500.00 2,200.00 500.00
				RM26,300.00

LEICA surveying instruments are manufactured under ISO9001 standard.

Yours faithfully

SURMAP SDN BHD

Steven Bong

Technical & Sales Manager

Steven Bong S. P.

H/p: 012-3303 589