

290

JR 102W CDH Lt 65770 (Plat 930)

No. Fail

Rajah di muka

Stesen	BEARING / SUDUT			Dari Stn	GARISAN		Ke Stn	Sudut Pukak (°)	Jarak	Suhu	Jarak Antara	Jarak Mukamat
	Penyalang Kiri	Penyalang Kanan	Purata		Bearing Mukamat							
	Jatim Sanpacle			22	2252139	21	4	35.527				35.527
				pt.B (RM)		pt.B (RM)						
22	21	2252139	952139	195315	22	195315	23	4	91.956			91.956
	23	195315	1995315									
		pt.B (RM)										
22-24	3983650			22	3983650	24	4	16.383			BKL	16.383
22-25	35310			22	35310	25	4	70.859			BKL	70.859
22-26	205717			22	205717	26	4	71.391			BKL	71.391
22-27	1192809			22	1192809	27	4	2.987			pt.LC	2.987
22-28	1923601			22	1923601	28	4	16.163			BKL	16.163
22-29	1295201			22	1295201	29	4	39.359			pt.L	39.359
29-30	785215			29	785215	30	4	36.361			pt.LC	36.361
29-31	1729709			29	1729709	31	4	13.916			AB	13.916
29-32	199596			29	199596	32	4	16.028			HWP	16.028
29-33	1001723			29	1001723	33	4	19.011			HWP	19.011
29-34	2821500			29	2821500	34	4	16.139			HWP	16.139

28-25 6 21 12 56.888 N
6 20 47 55.899 PO
+25' -0.006

28-26 18 36 33 57.381 N
18 36 31 57.391 PO 26
+2' -0.000

No. Fail.

Rajah di muka

