

JR/30 W 77A/

Rajah di muka

No. Fail

Rajah di muka												
No. Fail												
Stesen	BEARING / SUDUT			Dari Stn.	GARISAN		Ke Stn.	Sudut Pukak (°)	Jarak	Suhu	Jarak Antara Tugang	Jarak Muktamat
	Penyilang Kiri	Penyilang Kanan	Purata		Bearing Muktamat							
	Datum	Daripada		2	30/244	1	4	22272		27/6/2015		22272
				pk.B		pk.B	7BM					
1	30/244	12/244	9 1738	2	9 1738	3	4	39.939				39.939
2	3	9 1738	189 1738									
		pk.B										
2-4	330 0858	150 0858		2	330 0858	4	4	28.031		pk.L ←		28.031
2-5	330 3329			2	330 3329	5	4	18.919		pk.L ←		18.919
2-6	27 7052			2	27 7052	6	4	27.331		pk.L ←		27.331
2-7	30 7358			2	30 7358	7	4	29.963		pk.L ←		29.963
2-8	68 5820			2	68 5820	8	4	29.735		pk.B		29.735

Rajah di muka

WIKAYAH PERSEKUTUAN
MUKAM KACA CUMPAK
TANPA SKACA

Tarikh Aras
 Daripada J2130 7721

Dibuat untuk 78
 Ke

Pandangan Belakang	Pandangan Antara	Pandangan Hadapan	Naik	Turun	Aras Yang Dilaras	Jarak	Catitan
1.788 (5.72)	1.336 (8.38)	1.078 (3.54)			48.492	PC / GPS sh.	
	← 1.078 (3.54)	1.728 (5.67)			48.900	78m PC 2365 Adu Drain.	
					48.158	78m PC 2366 / Back lane	
					48.508	PC 1031	
1.798 (5.96)							
	1.112 (3.65)				53.323	CP BM	
					58.009	BM W0088 (Bunk 772)	
							GPS level on CP BM 53.401
							BM level 53.323
							70.078
							GPS level on PC 48.570
							+ constant - 0.078
							48.492