

No. Fail. JE 087W Chau Krt.

Rajah di muka

Stesen	BEARING / SUJUT			Dari Stn	GARISAN		Ke Stn	Sudut Pukak (°)	Jarak	Suhu	Jarak Antara Bang	Jarak Muktamad
	Penyalang Kiri	Penyalang Kanan	Purata		Bearing Muktamad							
	Datum	Danpadi		19 sh /ama	237 1930		11 sh /ama	4	37.332	11/7/2023		37.332
11	237 1930	57 1930	208 57 05	19	208 57 05	50		4	1.260			1.260
19	50	208 57 05	28 57 05									
	Demarcate.											
19-51	275 1019			19	275 1019	51		4	31.026	pk.B		31.026
19-52	189 5219			19	189 5219	52		4	22.961	pk.B		22.961
19-53	228 9918			19	228 9918	53		4	31.999 (71)	pk.B 71		31.999
19-54	237 3911			19	237 3911	54		4	38.297	pk.B		38.297
19-55	199 1127	(A3)		19	199 1127	55		4	22.852	(77)		22.852
19-56	223 0001	(B3)		19	223 0001	56		4	29.107	(77)		29.107
19-57	286 0639	(D3)		19	286 0639	57		4	31.272	(77)		31.272
19-58	299 1093	(C3)		19	299 1093	58		4	35.568	(77)		35.568

