

No. Fail JE/88W 1BIS +101e1

Rajah di muka

Stesen	BEARING / SUDUT			Dari Stn.	GARISAN		Ke Stn.	Sudut Pukak (±)	Jarak	Suhu	Jarak Antara Pangsang	Jarak Muktamat
	Penyilang Kiri	Penyilang Kanan	Purata		Bearing Muktamat							
○	Datum	Danpeda		1	272 025/	2	H	116.39/	13/5/2017			116.39/
					Aj Ak.							
					Aj1 M4							
1-3	78 7812			1	70 7812	3	H	59.29/			pk.L	59.29/
1-4	78 27 79			1	78 27 79	4	H	78.025			pk.L	78.025
1	62 025/	272 025/	193018	2	193018	5	H	58.726				58.726
2												
5	193018	1993018										
	pk.B											
2-6	62 1457			2	62 1457	6	H	73.926			pk.L (7C1)	73.926
2-7	72 1532			2	72 1532	7	H	73.580			pk.L (7C2)	73.580
2-8	72 7153			2	72 7153	8	H	78.819			pk.L	78.819
2-9	103 5577			2	103 5577	9	H	20.979			AjK	20.979
2-10	121 2127			2	121 2127	10	H	21.627			pk.L	21.627
2-11	121 1531			2	121 1531	11	H	28.380			pk.L	28.380
2-12	176 7177			2	176 7177	12	H	12.096			AM	12.096
2	1993018	193018	337 050/	5	337 050/	13	H	73.321				73.321
5												
13	337 050/	157 050/										
	pk.B											
13-14	282 531/			13	282 531/	14	H	30.087			pk.L	30.087
13-15	206 3700			13	206 3700	15	H	25.050			pk.L	25.050
13-16	206 1732			13	206 1732	16	H	73.337			pk.L	73.337
13-17	175 5707			13	175 5707	17	H	29.010			pk.L	29.010

Stesen	BEARING / SUDUT			Dari Stn.	GARISAN	Ke Stn.	Sudut Pukak (±)	Jarak	Suhu	Jarak Antara Tupang	Jarak Mukamat
	Penyilang Kiri	Penyilang Kanan	Purata		Bearing Mukamat						
19 PKCE											
13 PKB											
69 PA 20706											
70 PKCE											
15 PKCE											
18 PKL											
20003 PA 1108756											
5 PKB											
18											
6 PKC (C1)											
7 PKL											
8 PKCE											
20001 PA 1107733											
2 PKB											
9											
10 PKL											
11 PKCE											
20009 PA 1108826											
15-11	158 9856	91.586	✓				15 7 92	70 02	180.697	✓	
	158 9816	91.519	PO				92 70 51		180.700	PO	
	- 1 20"	70.027						- 79"	- 0.006		